## Wear & Repair Kits



# *Maintenance and Wear & Repair Kits*

# Pumps

Atlas Copco ISP Kits are sets of pre-assembled parts carefully selected to fit the preventative maintenance schedule of your pump.

This kit contains all necessary assembled components to facilitate and lower the cost of maintenance.

Our Wear & Repair kits are sets of individual components, selected on the basis of our experience, for the most common repair and replacement operations on your machine. Cost effective and convenient, these kits simplify the service process by ensuring you get what you need taking the advantage of having all necessary parts in one box.



#### **ISP Repair kits and seals**

Kit	Part Number
Instant Service Pack (ISP) WEDA 50 and 60	470W253362
Instant Service Pack WEDA 70	470W272041
Instant Service Pack WEDA 90	470W292054
Instant Service Pack WEDA 100	470W492020
Repair kit for ISP WEDA 50 and 60	4812050284
Repair kit for ISP WEDA 70	4812050285
Repair kit for ISP WEDA 90	4812050286
Repair kit for ISP WEDA 100	4812050287
Seal kit WEDA 30 and 40	4812050573

#### Set of Gaskets

Kit	Part Number
Set of gaskets WEDA 10	470W214879
Set of gaskets WEDA 30 and 40	470W743428
Set of gaskets WEDA 50L, N, H and 60N, H Set of gaskets WEDA 60S Set of gaskets WEDA 70 Set of gaskets WEDA 90 Set of gaskets WEDA 100	470W254495 470W254497 470W274414 470W294324 9822170236

#### Wear parts kit

Kit	Part Number
Wear parts kit for WEDA 10, 50hz	470W214880
Wear parts kit for WEDA 10, 60hz	470W214881
Wear parts kit for WEDA 30L, 50hz	470W224912
Wear parts kit for WEDA 30N, 50hz	470W224914
Wear parts kit for WEDA 30N, 60hz	470W224915
Wear parts kit for WEDA 40, 50hz	470W743434
Wear parts kit for WEDA 40, 60hz	470W743435
Wear parts kit for WEDA 50L, 50Hz	9822170212
Wear parts kit for WEDA 50L, 60Hz	9822170215
Wear parts kit for WEDA 50N, 50Hz	9822170213
Wear parts kit for WEDA 50N, 60Hz	9822170216
Wear parts kit for WEDA 50H, 50Hz	9822170214
Wear parts kit for WEDA 50H, 60Hz	9822170217
Wear parts kit for WEDA 60N, 50Hz	9822170218
Wear parts kit for WEDA 60N, 60Hz	9822170220
Wear parts kit for WEDA 60H, 50Hz	9822170219
Wear parts kit for WEDA 60H, 60Hz	9822170221
Wear parts kit for WEDA 60S, 50hz	470W254450
Wear parts kit for WEDA 60S, 60hz	470W254451
Wear parts kit for WEDA 70L, 50hz	9822170222
Wear parts kit for WEDA 70H, 50hz	9822170223
Wear parts kit for WEDA 90L, 50Hz	9822170226
Wear parts kit for WEDA 90L, 60Hz	9822170228
Wear parts kit for WEDA 90H, 50Hz	9822170227
Wear parts kit for WEDA 90H, 60Hz	9822170229
Wear parts kit for WEDA 100, 50Hz	9822170234
Wear parts kit for WEDA 100, 60Hz	9822170235

### Atlas Copco PowerTechnique Service atlascopco.com